



BW/85850

## Bath Armor™ replacement for water in water baths

- No more filling.
- No more routine cleaning.
- No water borne contamination.
- No longer incubating microbes.
- Washes and sterilizes easily.
- Good thermal heat distribution.
- Smooth, rounded & fluid-like

Replace water in your water bath with these thermally efficient pellets that are easy to keep clean. It enables you to eliminate nearly all water bath cleaning and protects your water bath from drying out. Saving need for racks, floaties and bottle weights. More free time, one less lab duty, never have to wash or refill a water bath again.

Cat. No.	Description
BW/85850	Bath Armor replacement for water in water baths, 5 Litre

*\*Larger 12 Litre pack size available*

## Calibration Record

The completed calibration record will be enclosed at the rear of the instruction book accompanying the Clifton unit carrying the following information:

- Unique record number for traceability.
- Serial number of the unit.
- Instrument it was checked against.
- Calibration temperature and actual sensitivity results.

The calibration record provides a measurement of precision about set point with maximum and minimum sensitivity readings obtained. Precision is defined as "(1) The ability of a measurement to be consistently reproduced" and "(2) The number of significant digits to which a value has been reliably measured".

The calibration record does not provide or assure any form of accuracy.

Cat. No.	Description
BW/85862	Calibration Record <i>Applicable for all Clifton models</i>




BW/85874

## Drain Tap

Providing a gated on/off valve to empty fluids conveniently from the bath.

With the new 'big bore' fast draining outlets it only takes 13 minutes to empty a 28 litre bath, 50% quicker than before.

Cat. No.	Description
BW/85874	Drain Tap Assembly to suit baths with serial number 7510 <i>For 22, 28 and 56 litre baths – not suitable for use with NE4 series baths</i>



BW/85260

## Reference thermometer

Thermometer clip with bent stem red spirit filled thermometer, lies flush with top edge of the bath to prevent accidental damage.

Technical Specifications	
Scale	0 - 100°C in 2°C graduations

Cat. No.	Code	Description
BW/85260	TC-1	Reference thermometer